

SEALING TRANSFORMER OIL VALVES WITH BELZONA

ID: 1518

Industry: Power
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon steel and plastic.
Products: * Belzona® 1161 (Super UW-Metal) ,

Customer Location: Electricity distribution, Vitoria, Spain
Application Date: December 2009.

Problem

Valves were leaking oil due to a defective flange seal.



Photograph Descriptions

- * General view of the location for the unit ,
- * Cleaning the application area. ,
- * Final result after application of Belzona® 1161 ,

Application Situation

Oil valves feeding a transformer at substation.

Application Method

The application was carried out according to the Belzona Know-How System Leaflet VPF-12,

Belzona Facts

Using Belzona surface tolerant material, the leak was stopped reducing maintenance costs and extending the service life of the equipment. Impact on the environment was also reduced.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve