

DUCT SEALING WITH BELZONA® 4211


ID: 153

Industry: General Industry
Application: VPF-Valves, Pipes and Fittings
Substrate: Concrete, rubber and PVC
Products: * Belzona® 4211 (Magma-Stop) ,

Customer Location: Telecommunications in India
Application Date: August 1999

Problem

Water leakage into the chambers causing cable joints to be submerged and extensive disruptions to telephone lines. Problem is particularly great during the monsoon.



Photograph Descriptions

- * Access to the chambers ,
- * The cable connections ,
- * & 4. Application of Belzona® 4211 underway ,

Application Situation

Underground chambers containing cable joints

Application Method

Application was carried out in accordance with Belzona System Leaflet VPF-11b suitably modified.

Belzona Facts

"Live" leaks were effectively sealed eliminating major disruption to the local and national communication systems.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve