

# BELZONA REPAIRS TO SPALLED CONCRETE

ID: 154

**Industry:** General Industry  
**Application:** RPA-Roof Problem Areas  
**Substrate:** Concrete and steel  
**Products:** \* Belzona® 4141 (Magma-Build) ,  
\* Belzona® 5151 (Hi-Build) ,

**Customer Location:** Art college in U.K.  
**Application Date:** 1996

## Problem

*Carbonation of the concrete allowing corrosion of the steel reinforcing leading in turn to serious spalling of the concrete.*



## Photograph Descriptions

- \* Some of the extensive spalling prepared and conditioned ,
- \* Belzona® 4141 applied to rebuild the spalled concrete ,
- \* Completed application ,

## Application Situation

Cast concrete perimeter roof detail

## Application Method

Application was carried out in accordance with Belzona System Leaflet RPA-2.

## Belzona Facts

Permanent repairs were carried out with minimum access time. Belzona coating will prevent further carbonation on surrounding areas.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve