

BELZONA PROVEN PROTECTION FOR SEDIMENTATION TANK

ID: 1574

Industry: *Buildings & Structures*
Application: *CEP-Centrifugal Pumps*
Substrate: *Steel*
Products: ** Belzona 5811 (Immersion Grade) ,*

Customer Location: *Pharmaceutical producer, Slovakia*
Application Date: *1998 to September, 2010*

Problem

The tanks suffer from severe corrosion.



Photograph Descriptions

- * Tank showing severe corrosion ,
- * Grit-blasting the tank ,
- * Setting up the spray equipment ,
- * Tank after the application ,

Application Situation

Open topped sedimentation tanks used for Ferric sulphate water clarification.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. The Belzona was applied using Airless spray equipment.

Belzona Facts

Since 1998 5 clarifier tanks have been coated for the pharmaceutical producer. Inspections after 10 years had shown that Belzona

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

5811 performed excellently. This proved a key influencing factor for the customer to choose Belzona again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

