

BELZONA FLOOR REPAIRS IN CIDER FACTORY

ID: 1575

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,

Customer Location: Cider Manufacturer, UK
Application Date: 2009

Problem

Lorry trailers park here and the stabilisers when lowered damage the floor area after 6-8 months.



Photograph Descriptions

- * Preparation of damaged area ,
- * Application of Conditioner ,
- * Applying Belzona® 4131 ,
- * Completed Application ,

Application Situation

Lorry park.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

The repairing and protection of the floor in these localised areas with Belzona® 4131 resists both impact and abrasion thus extending the life of the floor area leading to reduced maintenance. The customer was very pleased with the results and this job

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

has lead to several other applications being undertaken in the plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

