

# BELZONA PROVIDES LONG TERM SOLUTION IN COOL ROOMS

ID: 1578

**Industry:** General Industry  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** \* Belzona® 4131 (Magma Screed) ,  
\* Belzona® 2221 (MP Fluid Elastomer) ,  
\* Belzona® 5811 (Immersion Grade) ,

**Customer Location:** Poultry Plant, Virginia  
**Application Date:** 1995

## Problem

USDA inspectors made it clear that the leaks needed to be stopped. Floor needed to be repaired, coated and expansion joints sealed.



## Photograph Descriptions

- \* Second Floor Cooler ,
- \* After Original Application ,
- \* Floor After 14 Years ,
- \* Only Small Damage Present ,

## Application Situation

Second floor cooler (8500 ft<sup>2</sup>) was leaking onto the cooler on the lower floor.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & FPA-6.

## Belzona Facts

After 14 years the floor was still water proof and without any leaks. Some scratches were present due to metal wheeled fork lifts but no water penetration. Small areas were touched up. Customer was very happy with longevity of the application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

