

BELZONA RESTORES HYGEINE IN BOTTLING ROOM

ID: 1605

Industry: Buildings & Structures

Customer Location: Bottled Water Manufacturer, Perthshire, UK

Application: FPA-Floor Problem Areas

Application Date: September 2010

Substrate: Concrete

Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 5231 (S G Laminate) ,

Problem

There were several cracked and broken tiles. This created a potential hygiene problem and required rectifying to remove traps for bacteria and to aid cleaning.



Photograph Descriptions

- * Damaged tiles being repaired with Belzona® 4131 ,
- * Floor levelled with Belzona® 4131 ,
- * Light grey Belzona® 5231 being applied ,
- * Completed floor coating ,

Application Situation

Tiled floor in bottling room.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & 3. Belzona® 4131 was used to replace loose tiles sand create a uniform surface prior to application of the Belzopna® 5231.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Belzona Facts

The Belzona System creates a level, seamless surface that is hygienic in this critical area. The low VOC, low odour of the system was a further benefit in this bottling plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

