# ROUTINE BELZONA TANK BASE SEALING APPLICATION

ID: 1616

Industry: Buildings & Structures Customer Location: Refinery, Thailand
Application: CEP-Centrifugal Pumps Application Date: 2002- ongoing

Substrate: Steel, concrete

Products: \* Belzona® 3111 (Flexible Membrane System),

#### Problem

Bitumen sealant had failed to seal beneath the tank base allowing water pentration.









## **Photograph Descriptions**

- \* General view of the tank,
- \* Deteriorated bitumen being removed,
- \* Substrate conditioned,
- \* Belzona® 3111 being applied to complete the system,

## **Application Situation**

Fuel storage tanks

## **Application Method**

Application was carried out in accordance with Belzona® Know-How System Leaflets GSS-3.

#### **Belzona Facts**

The flexibility of the Tank Base Sealing System is ideally suited to operation in this hot tropical climate. This is one of more than 50 such tanks now protected with the Belzona Tank Base Sealing System.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve