

BELZONA PROVIDES COST EFFECTIVE SOLUTION TO CONVEYOR BELT REPAIRS

ID: 1621

Industry: General Industry

Customer Location: Waste Management Company,
Manchester UK

Application: SHM-Solids Handling Machinery

Application Date: August 2010

Substrate: Rubber

Products: * Belzona® 2311 (SR Elastomer) ,

Problem

An L shaped cut approximately 300mm across the length of the belt was found in a new conveyor belt.



Photograph Descriptions

- * Damaged conveyor belt - L shaped cut ,
- * Surface being prepared using a wire brush on a hand drill ,
- * Belzona Conditioner applied with 1 coat of product and reinforcing tape laid on top ,
- * Completed conveyor repair ,

Application Situation

The material recycling facility have several thin conveyor belts to enable the various separation processes. Unfortunately they can be damaged relatively easily and are costly and time consuming to replace.

Application Method

The application was carried out in accordance with Belzona Know-How system Leaflet SHM-1. Top cover was cut back before repairing with Belzona® 2311 incorporating Belzona® 9341 (Reinforcement Tape).

Belzona Facts

The cost of replacing a new belt is estimated at £600.00 plus labour. The Belzona repair solution cost approximately £39.00 in

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

materials offering a saving of £561.00 The whole process including preparation, repair and cure time took around 2 hour 15 minutes. The application was completed out of hours so as not to impact on production.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

