

# BELZONA SEALS PLANT ROOM FLOOR

ID: 1637

Industry: Buildings & Structures  
Application: CEP-Centrifugal Pumps  
Substrate: Concrete  
Products: \* Belzona® 5231 (SG Laminate) ,

Customer Location: Hospital, UK  
Application Date: May 2009

## Problem

Water was leaking through the floor to the operating theatres below.



## Photograph Descriptions

\* Damaged floor Belzona® 5231 application starting Completed application Completed application ,

\* ,

## Application Situation

Boiler plant room of a hospital

## Application Method

Application was carried out in accordance with Belzona Know How System Leaflet FPA-8. The floor was first diamond ground and then two coats of Belzona® 5231 (SG Laminate) applied.

## Belzona Facts

The whole application was carried out over one weekend. The low odour, solvent free Belzona® 5231 did not impact on normal operating of the hospital.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve