

BELZONA, THE EASY WAY TO SEAL SILOS

ID: 1639

Industry: Buildings & Structures
Application: CEP-Centrifugal Pumps
Substrate: Steel
Products: * Belzona 3111 (Flexible Membrane System) ,

Customer Location: Fire Protection Systems Manufacturer, UK
Application Date: August 2008

Problem

Corrosion and mechanical damage had opened up the bolted joints allowing rain water to wash dirt through the joints leading to contamination of the lime and chalk stored in the silos.



Photograph Descriptions

- * Silo scaffolded and ready for work to commence ,
- * Initial application to problem areas ,
- * Silo roof fully protected ,
- * Completed application ,

Application Situation

Two 17 metre high, 6 metre diameter silos for storage of Lime and Chalk

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1. After preparing substrate with grinders, Belzona® 3921 (GSC Conditioner) was applied before completing the application with two coats Belzona® 3111.

Belzona Facts

Belzona repairs have proven to be 100% successful and were completed at a fraction the cost of a new silo (£130K).

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve