

BELZONA OVERCOMES PROBLEM OF LEAD THEFT

ID: 1643

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Felt and slate*
Products: ** Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *Local School, UK*
Application Date: *2008*

Problem

This school had recently suffered from theft of the lead from their roof. The damage was so extensive that if not addressed, it would lead to structural defects resulting in a potentially disruptive high cost maintenance repair.



Photograph Descriptions

- * Window before application ,
- * General view of the roof ,
- * Application completed ,
- * Application completed ,

Application Situation

Window canopies on roof of a local school

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-2. Roof was felted prior to sealing with fully reinforced Belzona® 3111 system.

Belzona Facts

The repairs were completed in less than one week. Revisiting the application in 2010, the school has not experienced any further problems, and the repair is still in excellent condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve