

# BELZONA REPAIRS COLOUR MATCH SPALLED LINTELS

ID: 1681

**Industry:** Buildings & Structures  
**Application:** WPA-Wall Problem Areas  
**Substrate:** Concrete  
**Products:** \* Belzona® 4141 (Magma Build) ,

**Customer Location:** Local Education Authority, UK  
**Application Date:** September 2009

## Problem

Spalled concrete due to rebar corrosion.



## Photograph Descriptions

- \* Spalled concrete. ,
- \* Application in process using straight edge to form neat corner. ,
- \* Completing the application. ,
- \* Completed application. Note excellent colour match. ,

## Application Situation

Concrete lintels.

## Application Method

Application carried out in accordance with Belzona Know-How System Leaflet WPA-4. Belzona® 4141 was colour matched to existing concrete using Iron Oxide pigments.

## Belzona Facts

Repair was carried out quickly without need for scaffolding or permanent shuttering. Ability to colour match the repair ensured aesthetic acceptability.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve