Belzona refurnishes schools floor

ID: 1696

Industry:Buildings & StructuresCustomer Location: Cheltenham, UKApplication:FPA-Floor Problem AreasApplication Date: October 2010

Substrate: Concrete with an existing coating unknown

Products: * Belzona® 5231 SG Laminate,

Problem

They had a few slips on the existing floor and requires a quick curing application which could be carried out within four days start to finish with no solvant smells.









Photograph Descriptions

* Corridor prior to the application Kitchen prior to the application Corridor after application Kitchen after application ,

Application Situation

Floor of the corridor and kitchen of a private school

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. The application was carried out in three steps, mechanical abrasion, clean/degrease and then, two coats of Belzona® 5231.

Belzona Facts

They required a seamless systems, solvent free with 10% aggregate to provide a positive grip system which is also chemical resistance and quick curing for less down time.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve