

# BELZONA ATTENTION ON THE ROOF


ID: 172

**Industry:** General Industry  
**Application:** RPA-Roof Problem Areas  
**Substrate:** Conventional four ply build up roof and brick  
**Products:** \* Belzona® 3111 (Flexible Membrane) ,  
\* Belzona® 9311 (Membrane Reinforcing Sheet) ,

**Customer Location:** U.S. Air Force Base in Illinois, USA  
**Application Date:** July 1995

## Problem

*This building had been renovated, severe leaks were destroying new ceiling tiles and wallpaper. Flashings were pulled away from the wall and water gushed in.*



## Photograph Descriptions

- \* Belzona® 9311 (Membrane Reinforcing sheet) is pre-wetted prior to application. ,
- \* Second coat of Belzona® 3111 (Flexible Membrane) over first. ,
- \* The finishing touches. ,

## Application Situation

Roof

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflet RPA-8.

## Belzona Facts

240 linear feet by 2 feet wide was coated in five hours. One hour later, a heavy rain blew in, there were no leaks and no damage to the Belzona® 3111 (Flexible Membrane). The roof is now watertight.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve