

BELZONA CONTAINMENT DIKE SEALED

ID: 174

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete
Products: * Belzona® 4151 (Magma Quartz Resins),

Customer Location: Beer Manufacturer in Texas, U.S.A.
Application Date: February 1995

Problem

Previous coating had failed causing minor damage to the dike curb and pump pads.



Photograph Descriptions

- * The containment area. ,
- * Application of Belzona® 4151 (Magma Quartz Resins) nearing completion. ,
- * The containment area now protected with Belzona. ,

Application Situation

Sodium bicarbonate chemical tank containment area at brewery.

Application Method

Application was carried out in accordance with Belzona Know-How Leaflet TCC-15.

Belzona Facts

Previous vinyl ester coating had failed. Belzona® 4151 (Magma Quartz Resins) solved the problem. Sealing this containment area prevented possible leakage and shutdown of this critical operation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve