BELZONA SLIDES THE CHIPS OFF THE BARK SHAKER

ID: 182

Industry: Pulp & Paper Customer Location: Pulp Mill in Alabama, U.S.A.

Application: SHM-Solids Handling Machinery Application Date: 1992

Substrate: Carbon steel

Products: * Belzona® 1341 (Supermetalglide),

Problem

Bark builds up and clogs the shaker.







Photograph Descriptions

- * The bark shaker. ,
- * Belzona® 1341 provides a slick surface and the bark slides off. ,
- * Another view of the 30 foot long, 8-foot-wide bark shaker coated with two coats of Belzona® 1341. ,

Application Situation

Bark shaker sorts and distributes bark to the boiler.

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet SHM-13.

Belzona Facts

The application is touched-up every two years and prevents the bark from sticking to the steel. Recently, a new bark shaker has been coated. The customer is extremely happy with the application.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve