# **BELZONA PROTECTS EVAPORATOR TUBE SHEETS**

ID: 185

Industry: Pulp & Paper Customer Location: Pulp and paper mill in British Columbia,

Canada.

Application: HEX-Heat Exchangers Application Date: December 1995

Substrate: Stainless steel tubes and mild steel tube face.

Products: \* Belzona® 1391,

#### **Problem**

Erosion/corrosion of the tube sheet due to hot caustic (black liquor at 185°F) and galvanic corrosion due to dissimilar metals.







## **Photograph Descriptions**

- \* Inspection of previous coating shows degradation. ,
- \* One year of Belzona® 1391 coating exhibits no signs of degredation. ,
- \* Close-up view. Substrate is protected with Belzona® 1391.,

### **Application Situation**

Evaporator tube sheet.

## **Application Method**

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet HEX-1.

#### **Belzona Facts**

Belzona has been protecting evaporator tube sheets at this mill for several years. Erosion/corrosion is retarded. The life cycle of the equipment is extended and overall maintenance costs reduced.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve