

# BELZONA DOES FLOORS

ID: 186

**Industry:** General Industry

**Customer Location:** Beverage Canning Company in Mississippi, U.S.A.

**Application:** TCC-Tanks and Chemical Containment Areas

**Application Date:** January 1996

**Substrate:** Concrete

**Products:** \* Belzona® 4131 (Magma Screed) ,

## Problem

Extreme erosion surrounding drains due to acidic water discharge



## Photograph Descriptions

- \* Application commences, note the erosion of the concrete drain area. ,
- \* Application proceeds. ,
- \* Finished application, concrete protected and proper drainage restored. ,

## Application Situation

Chemical containment floor drainage area

## Application Method

Application was carried out in accordance with Belzona Know-How Leaflet TCC-9.

## Belzona Facts

Concrete would not hold up to the conditions. To remove the tanks and install a new floor would cost \$60,000 and require 2-3 weeks downtime. Preparation took 8 hours and the application of product took 8 hours. The customer saved \$50,000 by using Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve