

LONG TERM ROOF REPAIR BY BELZONA

ID: 1904

Industry: *Buildings & Structures*

Application: *RPA-Roof Problem Areas*

Substrate: *Asbestos*



Products: ** Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *Old private villa, Italy*

Application Date: *1985 and 2008*

Problem

Severely deteriorated asbestos roof tiles were no longer providing weather protection.



Photograph Descriptions

- * Damaged roof in 1985 ,
- * Roof application after 10 years in service ,
- * Close-up after 10 years in service ,
- * Refurbishment in 2008 again with Belzona® 3111 ,

Application Situation

Asbestos tiled roof of an old villa.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

Belzona Facts

After 10 years in service, the application was reviewed and still found to be in an excellent condition. Due to the reliable performance of Belzona, the customer opted again for Belzona® 3111 to refurbish the roof after 23 years service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

