

# BELZONA® 4131 REPAIRS TO SPALLED CONCRETE

ID: 203

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Concrete and stainless steel  
Products: \* Belzona® 4131 (Magma-Screed) ,

Customer Location: Local Authority  
Application Date: 1999

## Problem

*Extensive spalling had made using the hand-rail unsafe.*



## Photograph Descriptions

- \* General view of the site with specially boarded up Acrows insisted on by safety officials ,
- \* The degree of concrete damage clearly evident ,
- \* Rebuilding complete and gutter re-instated ,

## Application Situation

Canopy over a busy shopping area

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

## Belzona Facts

When work initially started damage was found to be more extensive than originally thought. Old railings were replaced. Rapid repairs with Belzona® 4131 ensured minimum disruption.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve