

BELZONA® 4131 REPAIRS TO SPALLED CONCRETE

ID: 203

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete and stainless steel
Products: * Belzona® 4131 (Magma-Screed) ,

Customer Location: Local Authority
Application Date: 1999

Problem

Extensive spalling had made using the hand-rail unsafe.



Photograph Descriptions

- * General view of the site with specially boarded up Acrows insisted on by safety officials ,
- * The degree of concrete damage clearly evident ,
- * Rebuilding complete and gutter re-instated ,

Application Situation

Canopy over a busy shopping area

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

Belzona Facts

When work initially started damage was found to be more extensive than originally thought. Old railings were replaced. Rapid repairs with Belzona® 4131 ensured minimum disruption.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve