

BELZONA SEALS SWIMMING POOL LEAKS

ID: 205

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4111 (Magma-Quartz),
* Belzona® 2211 (MP Hi-Build Elastomer),

Customer Location: Municipality
Application Date: August 1999

Problem

The original Silicone sealant had deteriorated allowing large water losses.



Photograph Descriptions

- * General view of the pool ,
- * Joint nosings rebuilt with tinted belzona® 4111 ,
- * Joint being masked prior to sealing with Belzona® 2211 ,

Application Situation

Expansion joints in swimming pool

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

Belzona Facts

Water losses were estimated to cost \$3,300 per month (replacement, heating and treatment). This type of application has been carried out for 14 years with great success. The Belzona® 4111 is tinted blue, grey and beige to match the pool design.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve