

BELZONA SEALS ACCESS RAMP LEAKS


ID: 2086

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas
Substrate: Concrete
Products: * Belzona® 3111 (Flexible Membrane) ,

Customer Location: Recreation Center, BC, Canada
Application Date: September 2002

Problem

The caulking between the walls and ramp base needed to be replaced on a regular basis to prevent water from entering into the area below.



Photograph Descriptions

- * View of joint to be sealed ,
- * Application of 1st coat of Belzona® 3111 incorporating Reinforcement Sheet ,
- * Completed application ,

Application Situation

Water was entering the storage and equipment areas below.

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet RPA-1.

Belzona Facts

Belzona® 3111 Flexible Membrane was used to create a flexible flashing between the wall and floor eliminating the previous repetitive maintenance with sealants.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024