

# BELZONA PROTECTS STRIPPER TOWER

ID: 21

**Industry:** Chemical & Petrochemical  
**Application:** TCC-Tanks and Chemical Containment Areas  
**Substrate:** Steel  
**Products:** \* Belzona® 1591 ,

**Customer Location:** Chemical Plant in Scotland  
**Application Date:** October 1998

## Problem

*Erosion/corrosion caused by steam together with chlorides and other impurities.*



## Photograph Descriptions

- \* General view of the Stripper Tower ,
- \* Application underway in the confined space of the Tower ,
- \* Application continues ,

## Application Situation

Stripper Tower used to clean waste-water. Steam is introduced at 180°C to remove hydrocarbons and other contaminants.

## Application Method

Application was carried out at a specialist applicators' works in accordance with Belzona Know-How Leaflet TCC-5.

## Belzona Facts

Original glass flake lining failed and protection required to keep the tower in service to next major shut-down.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve