

BELZONA® 3111 PROVEN PERFORMANCE

ID: 215

Industry: Chemical & Petrochemical
 Application: RPA-Roof Problem Areas
 Substrate: Asbestos and asphalt
 Products: * Belzona® 3111 (Flexible Membrane) ,

Customer Location: Chemical plant in the United Kingdom
 Application Date: 1986 and 1988

Problem

Severe water penetration, particularly through joints, seams, glazing units and gutters.



Photograph Descriptions

- * Work underway on the workshop roof ,
- * Horizontal area of office roof undergoing treatment ,
- * Completed application ,

Application Situation

Roof areas over offices and workshops.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, RPA-3 and RPA-6.

Belzona Facts

Belzona was chosen over other materials as previous repairs with competitive materials on the site had underperformed. Belzona system lived up to expectations and was in excellent condition when inspected in 1997.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA®
 Repair • Protect • Improve