

BELZONA PROTECTS DESULPHURIZATION UNITS


ID: 2158

Industry: Power
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona® 1391 (Ceramic HT),

Customer Location: Desulphurization unit, Powerplant, USA
Application Date: 2007

Problem

Corrosion by sulphurous gases at high temperatures.



Photograph Descriptions

- * Before the application ,
- * Application of Belzona® 1391 ,
- * Completed Application ,

Application Situation

Exhaust gas ducts of a smoke processing unit.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5

Belzona Facts

The application was achieved with minimal delay. The coating offers an excellent protection at high temperatures with proven experience in this type of FGD unit.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve