

BELZONA RAPID REPAIR TO VIADUCT RAILING SUPPORT

ID: 2161

Industry: General Industry

Application: FPA-Floor Problem Areas

Substrate: Concrete and steel

Products: * Belzona® 4141 (Magma-Build) ,

Customer Location: Town council, Canada

Application Date: May 2003

Problem

The concrete base for railings support pillars was cracked and spalled.



Photograph Descriptions

* Concrete condition before the application The concrete is coated with Belzona® 4911 Conditioner Belzona® 4141 application completed quickly and easily without the use of formwork ,

Application Situation

Pedestrian pavement beneath viaduct.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

Belzona Facts

The application was achieved in 2 hours and without the need for any formwork. This application is still in excellent condition when inspected in 2011.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve