

BELZONA KEEPS WORN HOSE WORKING

ID: 220

Industry: General Industry
Application: SOS-Ships and Offshore Structures

Customer Location: Shipping company in Canada
Application Date: November 2000

Substrate: Rubber
Products: * Belzona® 2311 (SR-Elastomer),

Problem

The uploading cement hose had worn through to the reinforcement wire.



Photograph Descriptions

- * Overview of damaged area ,
- * Loose pieces have been removed ,
- * The conditioner, reinforcement sheet and Belzona® 2311 (SR-Elastomer) have been used to fill area ,
- * The finished repair ,

Application Situation

Worn rubber hose

Application Method

Application was carried out out in accordance with Belzona Know-How System Leaflet SOS-12.

Belzona Facts

A quick reliable repair was required and other than replacement, Belzona was the only option.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025