

BELZONA REPAIRS WASTEWATER PUMP

ID: 234

Industry: Water / Wastewater

Customer Location: Wastewater treatment facility -
Vancouver, Canada.

Application: CEP-Centrifugal Pumps


Application Date: 1989

Substrate: Steel

Products: * Belzona® 1311 (Ceramic R-Metal) ,

Problem

Pumps were suffering from severe erosion around the volute. It was difficult to remove the unit for repair due to its size and location.



Photograph Descriptions

- * Large centrifugal pumps ,
- * Pumps disassembled for repair ,
- * Volute rebuilding in progress ,
- * Rebuilding in progress ,

Application Situation

Large six foot diameter centrifugal pumps.

Application Method

Application was carried out out in accordance with a modified version of Belzona Know-How System Leaflet MPT-2.

Belzona Facts

Pumps were opened five years after application and were in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve