

BELZONA REPAIRS COLLEGE STEPS

ID: 2451

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 4411 (Granogrip) ,

Customer Location: College, East Midlands, UK
Application Date: August 2011

Problem

Heavy foot traffic and weathering caused the steps at this college to become damaged and worn.



Photograph Descriptions

- * General view of the damaged steps ,
- * First application of Belzona® 4131 ,
- * Application being carried out ,
- * Finished application ,

Application Situation

Damaged steps at public college

Application Method

Application was carried out in accordance with the Belzona Know-How System Leaflets FPA-1 and FPA-8

Belzona Facts

Belzona products were required in order to give a fast, long-lasting and cost-effective repair. The ability to bond to and build up old concrete meant that the steps did not have to be completely removed and rebuilt. Belzona® 4411 was applied to the step nosings to provide a safety grip system and to ensure there was a contrast in colour, in order to meet the current DDA regulations regarding partially sighted people.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve