

BELZONA REPAIRS ARMY VEHICLE


ID: 2452

Industry: *Military*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Cast Aluminium*
Products: ** Belzona® 1161 (Super UW-Metal) ,*

Customer Location: *British Army, UK*
Application Date: *2010*

Problem

The vehicle's gearbox casting was porous leading to unacceptable oil loss.



Photograph Descriptions

- * The Jackal ,
- * The porous gearbox casting before application ,
- * The gearbox sealed with Belzona® 1161 ,

Application Situation

The Jackal, a high mobility army vehicle used in Afghanistan by the British Army

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1.

Belzona Facts

The Belzona repair was completed without heat and without removing the gearbox. Belzona® 1161 surface tolerant properties makes it ideal for this type of repair where oil contamination may be difficult to completely remove.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve