

# BELZONA SECURES THE TOWN HALL STEPS

ID: 2477

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Tiles  
Products: \* Belzona® 4111 (Magma-Quartz) ,  
\* Belzona® 4411 (Granogrip) ,

Customer Location: Town hall, France  
Application Date: February 2006

## Problem

*The steps were damaged through impact and were extremely slippery when wet.*



## Photograph Descriptions

- \* Close view of the damaged steps ,
- \* Side view of the steps ,
- \* Steps rebuilt with Belzona® 4111 ,
- \* Completed application with Belzona® 4411 grip system applied to leading edges ,

## Application Situation

Entrance steps to the town hall.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-8 & FPA-1. The steps were rebuilt with Belzona® 4111. A 3cm wide strip of Belzona® 4411 grip system was applied to the leading edge of the steps to create a non-slip surface.

## Belzona Facts

The Belzona repairs improved the entrance to the town hall both in its appearance and the safety for its users.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve