

BELZONA SECURES THE TOWN HALL STEPS

ID: 2477

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Tiles
Products: * Belzona® 4111 (Magma-Quartz),
* Belzona® 4411 (Granogrip),

Customer Location: Town hall, France
Application Date: February 2006

Problem

The steps were damaged through impact and were extremely slippery when wet.



Photograph Descriptions

- * Close view of the damaged steps ,
- * Side view of the steps ,
- * Steps rebuilt with Belzona® 4111 ,
- * Completed application with Belzona® 4411 grip system applied to leading edges ,

Application Situation

Entrance steps to the town hall.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-8 & FPA-1. The steps were rebuilt with Belzona® 4111. A 3cm wide strip of Belzona® 4411 grip system was applied to the leading edge of the steps to create a non-slip surface.

Belzona Facts

The Belzona repairs improved the entrance to the town hall both in its appearance and the safety for its users.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve