

BELZONA PROTECTION OF WATER INJECTION SPOOLS

ID: 248

Industry: Oil & Gas

Application: VPF-Valves, Pipes and Fittings

Substrate: Steel

Products: * Belzona® 1341 (Supermetalgilde) ,

Customer Location: Oil producer in Oman

Application Date: May 2000

Problem

Severe erosion/corrosion on internal of pipe spools due to brackish water which contains sand and H₂S.



Photograph Descriptions

- * Spools for coating ,
- * Application underway ,
- * Completed application ,
- * Completed application ,

Application Situation

Water injection header designed to operate up to 50°C.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-2.

Belzona Facts

Belzona has been protecting this type of equipment for several years. The life cycle of the spools is extended and overall maintenance reduced.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024


BELZONA®
Repair • Protect • Improve