

BELZONA PROTECTS DUCTWORK ELBOW

ID: 2485

Industry: Pulp & Paper

Customer Location: Paper Processing Industry, Gateshead, UK

Application: SHM-Solids Handling Machinery

Application Date: October 2011

Substrate: Steel Pipe

Products: * Belzona® 1111 (Super Metal) ,
* Belzona® 1812 (Ceramic Carbide FP) ,

Problem

The ducting had been installed early 2011 and due to the nature of their process/products the pipe elbows had worn within a short period of time.



Photograph Descriptions

- * Holed elbow ,
- * Plates bonded over holes using Belzona® 1111 ,
- * Internal bend coated with Belzona® 1812 ,
- * Duct elbow back in service ,

Application Situation

Ductwork elbows in pneumatic processed paper handling system.

Application Method

Application was carried out in accordance with Belzona System Leaflet SHM-8. The holed elbows were repaired using cut to size steel plates, formed and bonded over the holes using Belzona® 1111. The internal bend section was then lined with Belzona® 1812 to provide optimum abrasion resistance.

Belzona Facts

Pipe elbows have been and continue to be protected with Belzona, increasing the working life of the system. As a result the customer has saved money on replacement costs and downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve