

BELZONA KEEPS THE TRAFFIC MOVING: FOUR YEARS AND GOING STRONG

ID: 262

Industry: General Industry

Customer Location: Local municipality in British Columbia, Canada

Application: GSS-Gaskets, Seals and Shims

Application Date: March 1997

Substrate: Concrete and Steel

Products: * Belzona® 1211 (E-Metal) ,

Problem

Continuous impact from traffic damaged the outer concrete ring seat causing problems. The traffic could not be disrupted for an extended period of time.



Photograph Descriptions

- * Close look at the damage prior to Belzona repair ,
- * Completed job, still in service after four years ,

Application Situation

Valve well cover ring seat, located on a busy road.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-7.

Belzona Facts

The Belzona solution allowed the city to reset the valve well and manhole covers before further damage occurred, with the least amount of material and traffic disruption.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

