

BELZONA REPAIRS SUBWAY HANDRAIL

ID: 27

Industry: General Industry

Application: SHM-Solids Handling Machinery

Customer Location: Subway Station in Quebec, Canada

Application Date: March 1993

Substrate: Rubber and nylon fabric

Products: * Belzona® 2311 (SR-Elastomer) ,

Problem

Due to vandalism, a chunk of rubber was missing from the handrail.



Photograph Descriptions

- * The damage due to the vandalism ,
- * Application of Belzona® 2311 (SR-Elastomer) in progress ,
- * The finished repair ready for operation ,

Application Situation

Handrail of escalator at a subway station

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet SHM-1.

Belzona Facts

The repair was completed with \$50.00 of Belzona product. The alternative was hot vulcanizing which would have shut the escalator down for one day and cost approximately \$2,000. The repair took only two hours to perform, and after three years, is still in operation today.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024