

BELZONA NON-SKID SYSTEM REMOVES SLIP AND FALL HAZARD

ID: 289

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Quarry Tile
Products: * Belzona® 1321 (Ceramic S- Metal) ,
* Belzona® 9221 (Surefoot Aggregate) ,

Customer Location: Hospital in British Columbia, Canada
Application Date: 1997

Problem

The floor was plagued with constant complaints arising from slippery floor tiles. Non-skid tape safety pads were in use in strategic areas, but were constantly delaminating from the wet environment and harsh cleaning chemicals.



Photograph Descriptions

- * Surface preparation with template ,
- * Glaze removed from quarry tile floor ,
- * Masking tape removed after the application is complete ,
- * Completed application of grip system ,

Application Situation

Quarry tiled floor in a hospital dish washing area.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8.

Belzona Facts

It was found that the Belzona system initially cost about 30% more, but eliminated the need for replacement pads. The application has been in service for 5 years with no required maintenance.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve