# BELZONA IMPROVES PROTECTION AT BASE OF CHIMNEYS

ID: 2946

Industry: Power Customer Location: Municipality, Sweden
Application: ENC-Engines and Casings Application Date: September 2011

Substrate: Steel and concrete

Products: \* Belzona® 3211 (Lagseal),

\* Belzona® 5811 (Immersion Grade),

#### Problem

The chimneys are made of steel and are resting on a concrete base. Moisture between the chimney and the supporting concrete resulted in corrosion taking place on the chimney as well as a high risk for frost heave in the concrete.









## **Photograph Descriptions**

- \* Chimney Base for the furnace before the repair,
- \* Application of Belzona® 3211,
- \* Reinforcement sheet incorporated into the Belzona® 3211 coating bridging the steel/concrete junction,
- \* The finished application with Belzona® 5811 providing corrosion protection on the steel chimney,

## **Application Situation**

Three Chimneys for furnaces.

#### Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets GSS-3 and TCC-5. After grit blasting the repair area, the steel was protected with Belzona® 5811 and the Belzona® 3211 reinforced system was applied across the junction between steel and concrete.

### **Belzona Facts**

Belzona micro-porous Membrane systems are extennsively used to provide weather-proofing of tank bases so as to prevent under-tank corrosion, the same arrangement and problems as found on these chimneys. The system prevents water entering whilst allowing any existing moisture to dry out.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.



www.belzona.com