

BELZONA HELPS TO KEEP WORKSHOP CLEAN AT CIDER PLANT

ID: 2954

Industry: *General Industry*

Application: *WPA-Wall Problem Areas*

Substrate: *Steel and brick*

Products: ** Belzona® 5111 (Ceramic Cladding) ,
* Belzona® 5911 (Ceramic Conditioner) ,*

Customer Location: *Cider Producer, Herefordshire, UK*

Application Date: *June 2011*

Problem

Customer was looking for a product that they could wipe clean, have chemical resistance and brighten up a dull workshop.



Photograph Descriptions

- * Application of Belzona® 5911 Conditioner ,
- * Application of First Coat of Belzona® 5111 ,
- * Completed application ,
- * New brighter, cleaner working area ,

Application Situation

Engineers workshop in cider plant

Application Method

Application was carried out in accordance with Belzona System Leaflet WPA-2

Belzona Facts

Belzona® 5111 was the only product they could find to fill all of their requirements. Its excellent chemical and abrasion resistance allows for easy cleaning enabling clean bright environment to be maintained.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve