

BELZONA HEALS HOSPITAL EXPANSION JOINTS

ID: 297

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 4411 (Granogrip) ,
* Belzona® 2211 (MP Hi-Build) ,

Customer Location: Hospital in North Carolina, U.S.A.
Application Date: July 1993

Problem

Deteriorated expansion joints cause problems with x-ray equipment as well as with individuals tripping throughout the hallways.



Photograph Descriptions

- * Joint indentation evident through carpet ,
- * Concrete nosings spalled from traffic ,
- * Nosing rebuilt and joint sealed ,
- * Completed application ready for traffic ,

Application Situation

Deteriorated expansion joints throughout hospital hallways.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and FPA-6.

Belzona Facts

In all, seven joints have been refurbished using this Belzona System. This particular facility is a long term user of various Belzona Systems and was aware of the longevity of Belzona repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

