

# HOSPITAL KITCHEN REPAIRED WITH BELZONA

ID: 298

**Industry:** General Industry  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Quarry tile and concrete  
**Products:** \* Belzona® 4131 (Magma Screed) ,  
\* Belzona® 2211 (MP Hi-Build) ,  
\* Belzona® 4151 (Magma Quartz Resins) ,

**Customer Location:** Hospital in North Carolina, U.S.A.  
**Application Date:** Winter 2000

## Problem

The metal expansion joint in the kitchen of this hospital had failed and the deterioration caused interruption in cart movement over the irregular sur-face.



## Photograph Descriptions

- \* Damaged metal expansion joint ,
- \* Finished application with Belzona® 4151 recently applied ,
- \* Nosing fully cured and ready for traffic ,

## Application Situation

Metal expansion joint or slip joint in hospital kitchen floor.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and FPA-6.

## Belzona Facts

The red Belzona® 4131 (Magma Screed) gives the repair area a close color match to the original quarry tile floor.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve