

BELZONA FOR MUD PUMPS

ID: 3

Industry: Oil & Gas

Customer Location: Offshore oil drilling platform in the Gulf of Mexico.

Application: CEP-Centrifugal Pumps


Application Date: July 1995

Substrate: Cast iron

Products: * Belzona® 1311 (Ceramic R-Metal) ,
* Belzona® 1321 (Ceramic S-Metal) ,

Problem

Severe erosion.



Photograph Descriptions

- * Severe wear on the pump casing. ,
- * Forming technique and Belzona® 1311 (Ceramic R-Metal) used to rebuild the intake. ,
- * Two coats of Belzona® 1321 (Ceramic S-Metal) applied. Several pumps have been refurbished. ,

Application Situation

Mud pumps, casings and wear plates.

Application Method

The application was carried out in accordance with Belzona Know-How Leaflets CEP-3 and CEP-5.

Belzona Facts

The use of Belzona doubled the life of the casing and saved the replacement costs. Originally, the equipment lasted 3 months before being discarded and now it lasts 6 months and can be refurbished again and again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve