

BELZONA SOLVES WATER INGRESS ISSUE AT UNIVERSITY MACHINE SHOP

ID: 3013

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas
Substrate: Concrete and Brick
Products: * Belzona® 3131 (WG Membrane) ,
* Belzona® 9221 (Surefoot Aggregate) ,

Customer Location: University, Manchester, UK.
Application Date: October 2011

Problem

There had been ongoing water ingress issues into the lab machine shop over several years. A new drain had been inserted into the courtyard walkway approximately 18 months previous but the water ingress issues had deteriorated further rather than improve.



Photograph Descriptions

- * Initial inspection of the courtyard walkway and drain ,
- * Initial inspection of the Lab workshop directly under the courtyard walkway ,
- * Belzona® 3131 application in progress ,
- * Completed application ,

Application Situation

Courtyard walkway with surface water drain, the source of water ingress into laboratory machine shop below.

Application Method

Application was carried out in accordance with modified versions of Belzona Know-How System Leaflets RPA-6 and RPA-8. The system comprised three coats of Belzona® 3131 with the third coat blinded out with Belzona® 9221 aggregate to improve abrasion resistance and provide positive grip

Belzona Facts

The application was completed within 4 days and has eliminated water ingress. In addition to eliminating the water ingress, by applying a third coat of Belzona® 3131 and blinding out with Belzona® 9221 surefoot aggregate, a positive grip system has been

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

created which is both practical in reducing slip risk and pleasing to the eye. The alternative could have been to remove the drain, recut the concrete deck and replace. This would have proved a very lengthy, disruptive and costly procedure with no guarantee of success.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

