

BELZONA REPAIRS HYDRAULIC RAM IN SERVICE FOR OVER TEN YEARS

ID: 310


Industry: *Pulp & Paper*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Paper Mill in Alabama, USA*
Application Date: *1989*

Substrate: *Chromed Steel*
Products: ** Belzona® 1111 (Super Metal) ,*

Problem

The hydraulic ram was scored due to a packing failure and was unable to build up enough pressure to raise and lower the table and transfer the stack of paper onto the conveyor system.



Photograph Descriptions

- * Scored hydraulic ram cylinder ,
- * Surface preparation with die grinder ,
- * Damaged area squared off ,
- * Finished repair ,

Application Situation

Hydraulic ram for a Layboy Table.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-3.

Belzona Facts

The edges of the scores were squared off and deepened with a side grinder. Belzona® 1111 (Super Metal) was then applied to the prepared surface and dressed down with a file and emery cloth. The application has been in service for over 10 years. As long as the packing and seal area is maintained, the repair should last for a very long time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve