

BELZONA HAS SMASHING SUCCESS WITH THIS BULLDOZER REPAIR

ID: 311


Industry: General Industry
Application: MPT-Mechanical Power Transmission

Customer Location: Construction company in Florida USA
Application Date: 1992

Substrate: Chromed Steel
Products: * Belzona® 1111 (Super Metal) ,

Problem

During operation, the ram contacted a high voltage line, blowing out a section of the original chrome and steel. The damage was significant enough that the cylinder was no longer able to contain the hydraulic pressure.



Photograph Descriptions

- * Damage to hydraulic ram cylinder ,
- * Surface preparation with side grinder ,
- * Application of Belzona® 1111 (Super Metal) ,
- * Finished application after dressing down the repair ,

Application Situation

Hydraulic ram cylinder for a bulldozer.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-3.

Belzona Facts

The replacement cylinder cost in excess of \$800 in 1992 and following this successful repair, the construction company became a regular, satisfied customer.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve