

BELZONA GETS HEAVY EQUIPMENT BACK IN SERVICE, FAST!

ID: 312

Industry: General Industry
Application: MPT-Mechanical Power Transmission

Customer Location: Heavy equipment shop in Florida, USA
Application Date: 1983

Substrate: Chromed Steel
Products: * Belzona® 1111 (Super Metal) ,

Problem

Small pieces of rock worked their way underneath the seal and scored the hydraulic ram of this front end loader. Since hydraulic pressure was not able to be maintained, this piece of equipment was out of service.



Photograph Descriptions

- * Damaged hydraulic ram ,
- * Close-up and extension of cylinder damage ,
- * Surface preparation with small grinder ,
- * Dressing down the repair ,

Application Situation

Scored hydraulic ram for a front end loader.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet MPT-3.

Belzona Facts

Construction companies lose large sums of money when equipment is down during a project.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve