

BELZONA RESTORES THE PROPER SURFACE PROFILE TO A PRESS ROLL

ID: 318

Industry: *Pulp & Paper*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Paper Mill in Minnesota, USA*

Application Date: *1999*

Substrate: *Rubber lined steel*

Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Belzona® 1111 (Super Metal) was used to repair the damaged surface of the press roll after a metal bolt had gone through the machine. The roll was then unable to remove water from the paper. This produced poor quality paper and resulted in breaks.



Photograph Descriptions

- * Applying Belzona® 1111 (Super Metal) to damaged press roll ,
- * Removing excess Belzona from repair area ,
- * Machining repair to tolerances ,
- * Final rectification to maintain proper surface finish. ,

Application Situation

Press roll surface profile.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

Belzona Facts

After an initial cure of 2-hours, the material was machined and subsequently rectified to obtain the appropriate surface finish. Belzona® 1111 (Super metal) P&J hardness of between eight and nine closely matched the existing rubber hardness of the roll.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve