

SCRUBBER FILTER FRAMES REPAIRED PROTECTED WITH BELZONA

ID: 3317

Industry: General Industry

Application: TCC-Tanks and Chemical Containment Areas

Substrate: Stainless steel

Products: * Belzona® 1311 (Ceramic R-Metal) Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Phosphoric acid producer, Morocco

Application Date: January 2012

Problem

The environment contains up to 2,6 mg/Nm³ phosphoric acid which leads to severe corrosion problems.



Photograph Descriptions

* Scrubber filter frame before the application Filter frame gritblasted Application in progress Application to one of the scrubber filter frames completed. ,

Application Situation

20 scrubber filter frames from a gas filtering unit. Each unit made from 316L stainless steel had a surface area of 2.9m².

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5. For the coating application, the standards DIN 28051, 28053 and 55128 were applied. Before the application, the surfaces were gritblasted to a minimum depth of profile of 75 microns.

Belzona Facts

The customer already knew Belzona and wanted to protect his filters with Belzona® 1321 which has the required acid and erosion resistance. The filters were repaired and protected in just three days which met the clients tight schedule.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024